


MAN 37 PINS PLUG DIAGNOSE



PIN D = +12V

PIN A = GROUND

PIN a = K Line

